Location			OGUN &EKITI STATE			
Electrical refurbishments across 12 sites						
S/N	LOCATION	DESCRIPTION OF ITEM	QTY	UNIT	U/PRICE	AMOUNT
1	Oba Adejulugbe General Hospital, Ado Ekiti, Ekiti State	Replace one unit, inverter Air conditioner outdoor unit - 1HP LG	1	Nr		
2	State Hospital Ilaro, Ogun State	Purchase and install one unit 1hp inverter air conditioner	1	Unit		
3	State Hospital Isara, Ogun State	Purchase and install one unit 1hp inverter air conditioner	1	Unit		
4	Primary Health Center, Ota, Ogun State	Purchase and installation of 12 new 200AH Gel inverter batteries	12	Units		
5	State Hospital Ijebu Ode, Ogun State	Purchase and installation of 12 new 200AH Gel inverter batteries	12	Units		
		Purchase and installation of DC Combiner and components	3	Unit		
6	State Hospital Ijebu Igbo, Ogun State	Purchase and installation of 120amp charge controller	1	Unit		
		Purchase and installation of 10KVA Automatic Voltage Regulator	2	Unit		
7	GH Idiroko, Ogun state	Purchase and Installation of 5KVA 48V Online Inverter	1	unit		
8	GH Idiroko, Ogun state	Purchase and installation of 12 new 200AH Gel inverter batteries	12	unit		
9	GH Idiroko, Ogun state	Purchase and installation of DC Combiner and components	1	unit		
10	GH Ifo, Ogun state	Repair of Inverter AC: General Servicing and replacement of bad capacitors, relays and compressor		unit		
11	SH Ijaiye, Ogun state	Purchase and Installation of 5KVA 48V Online Inverter	1	unit		
12	SH Ijaiye, Ogun state	Purchase and installation of 12 new 200AH Gel inverter batteries	12	Units		
13	SH Ijaiye, Ogun state	Purchase and installation of DC Combiner and components	1	unit		
14	FMC Abeokuta, Ogun state	Purchase and Installation of 5KVA 48V Online Inverter	1	unit		
15	FMC Abeokuta, Ogun state	Purchase and installation of 10KVA Automatic Voltage Regulator	1	Unit		
16	GH Owoade Egba, Ogun state	Repair of Inverter AC: General Servicing and replacement of bad capacitors, relays and compressor		unit		
17	OOUTH Sagamu, Ogun state	Repair of Inverter AC: General Servicing and replacement of bad capacitors, relays and compressor		unit		